EMORY L. BROWN, JR.
ROUTE 4, BOX 82
FARMINGDALE, NEW JERSEY 07727

General Correspondence No. 49

December 2, 1968

National Rifle Association of America
1600 Rhode Island Avenue, N. W.
Washington, D. C.
20036

Gentlemen:

I bought an old M-91/38 Mannlicher-Carcano (6.5x52MM0) and had a Weaver C-4 Scope mounted on it usuing a Weaver N-3 side mount. When I tried to zero it in at fifty yards from bench-rest, I discovered that even with the maximum adjustment on the elevation knob (scope has to be rotated in the mount in order to load) the bullets still went low. I was usuing an NRA 25 yard pistol target with a two foot strip of newspaper attached to the bottom. None of the bullets even struck the paper. Can you tell me why this type of telescopic sight can not be adjusted so that I can make hits on theetarget paper?

Sincerely,

17 WO7727BROJERR4B 3347 MAR 69

Emory L Brown Jr